

INSPECTION SHEET 検品書
LIFTING PLATFORM 高所作業車

INSPECTION DATE	2026/2/24	MAKE	TADANO	MODEL	AT-270-2
SERIAL No.	PLATE : 371352			STAMP : 371352	
HR METER	1510	HR	Odometer	4279	km
YEAR					YR
CHASSIS	MODEL TKG-FRR90S1			No. 7113120	
SHOE				TIRE SIZE	215/70R17.5
MAX HIGHT	27.0		m	MAX WEIGHT	200 kg

ENGINE : MODEL 4HK1 S/N 607969	
Oil leakage	<input type="radio"/> FAIR · Attn
Blow-By	<input type="radio"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	<input type="radio"/> FAIR · Attn
Oil	<input type="radio"/> FAIR · Attn
Exhaust Color	<input type="radio"/> FAIR · Attn
US EPA	YES <input type="radio"/> NO <input checked="" type="radio"/>
OPERATION PUMP	
Sound	<input type="radio"/> FAIR · Attn
Oil leakage	<input type="radio"/> FAIR · Attn
Power	<input type="radio"/> FAIR · Attn
COOLING SYSTEM	
Radiator	<input type="radio"/> FAIR · Attn
Oil Cooler	<input type="radio"/> FAIR · Attn
TRANSMISSION & TRAVEL	
T/M TYPE	AT <input type="radio"/> MT <input checked="" type="radio"/> No. OF GEARS 6 GEARS
Transmission	<input type="radio"/> FAIR · Attn
4WD	4WD <input type="radio"/> 2WD <input checked="" type="radio"/>
Travel	<input type="radio"/> FAIR · Attn
Swing	<input type="radio"/> FAIR · Attn
FOOT BRAKE	<input type="radio"/> FAIR · Attn
PARKING BRAKE	<input type="radio"/> FAIR · Attn
BOOM	
No. of Section	4 SECTIONS
DERRICKING CYL.	<input type="radio"/> FAIR · <input checked="" type="radio"/> Attn 油漏れあり OIL LEAKING
EXTENSION CYL.	<input type="radio"/> FAIR · Attn

INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · <input checked="" type="radio"/> FAIR · DIRTY
Operator's Seat	<input type="radio"/> FAIR · Attn
Glasses	<input type="radio"/> FAIR · Attn
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None
UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
TIRE WEAR	FAIR · <input checked="" type="radio"/> WORN · UNEVEN WEAR
COMMENT	
OUTRIGGERS X · <input checked="" type="radio"/> H	
OUTRIGGERS COND.	<input type="radio"/> FAIR · Attn
COMMENT	
バケット首振りガタあり BUCKET SWING: LOOSE	
リペイントあり REPAINTED	
最高出力 MAXIMUM OUTPUT: 140kW (190PS)/2600rpm	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。