

INSPECTION SHEET 検品書
LIFTING PLATFORM 高所作業車

INSPECTION DATE	2026/3/30	MAKE	TADANO	MODEL	AT-170-1
SERIAL No.	PLATE : 230273			STAMP : 230273	
HR METER	6255	HR	Odometer	87479	km
YEAR					YR
CHASSIS	MODEL KK-FE53EC			No. 561125	
SHOE				TIRE SIZE	7.00R16
MAX HIGHT	17.0		m	MAX WEIGHT	200 kg

ENGINE : MODEL S/N	
Oil leakage	FAIR (Attn) *1
Blow-By	FAIR (Attn) A LITTLE · MIDDLE · SEVERE
Sound	FAIR (Attn)
Oil	FAIR (Attn)
Exhaust Color	FAIR (Attn)
US EPA	YES (NO)
OPERATION PUMP	
Sound	FAIR (Attn)
Oil leakage	FAIR (Attn)
Power	FAIR (Attn)
COOLING SYSTEM	
Radiator	FAIR (Attn)
Oil Cooler	FAIR (Attn)
TRANSMISSION & TRAVEL	
T/M TYPE	AT (MT) No. OF GEARS 5 GEARS
Transmission	FAIR (Attn)
4WD	4WD (2WD)
Travel	FAIR (Attn)
Swing	FAIR (Attn)
FOOT BRAKE	FAIR (Attn)
PARKING BRAKE	FAIR (Attn)
BOOM	
No. of Section	3 SECTIONS
DERRICKING CYL.	FAIR (Attn)
EXTENSION CYL.	FAIR (Attn)

INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · FAIR (FAIR) · DIRTY
Operator's Seat	FAIR (Attn)
Glasses	FAIR (Attn)
AirCon	(A/C) · H/C · H only · C only · None
UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	FAIR (FAIR) · WORN · UNEVEN WEAR
COMMENT	
OUTRIGGERS X · (H)	
OUTRIGGERS COND.	FAIR (Attn)
COMMENT	
リペイントあり REPAINTED	
カゴ首振りガタあり BUCKET: LOOSE TO SWING	
*1 ブロック周り、ヘッドガスケットにじみあり	
*1 AROUND ENGINE BLOCK & HEAD GASKET: OIL OOZING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。